



## Unacceptable Waste Diverted From Miramar Landfill

Black powder



## Unacceptable Waste Diverted From Miramar Landfill

Medical waste containing liquid blood



## Unacceptable Waste Diverted From Miramar Landfill

Pigments from a printing company





## **Unacceptable Waste Diverted From Miramar Landfill**

Industrial cleaning products and lubricants from a trucking company



## **Unacceptable Waste Diverted From Miramar Landfill**

Hazardous waste solvent from a body shop





## Unacceptable Waste Diverted From Miramar Landfill

Muriatic acid from a pool construction company



## Unacceptable Waste Diverted From Miramar Landfill

Paint, solvents, and paint related waste from a theater





## **Unacceptable Waste Diverted From Miramar Landfill**

Asbestos containing acoustic ceiling material





## **Unacceptable Waste Diverted From Miramar Landfill**

Paint waste from a construction company



## **Unacceptable Waste Diverted From Miramar Landfill**

Fluorescent light bulbs





## **Unacceptable Waste Diverted From Miramar Landfill**

Lead Paint Chips



## **Unacceptable Waste Diverted From Miramar Landfill**

PCB containing light ballasts from an electrical company





## **Unacceptable Waste Diverted From Miramar Landfill**

Approximately 2,000 fluorescent light bulbs from a building retrofit disposed at Miramar Landfill prior to cleanup



## **Unacceptable Waste Diverted From Miramar Landfill**

Paint from a painting contractor disposed at Miramar Landfill prior to cleanup